

# RD 830 LEVEE INSPECTION

DATE: 1/10/20	TIME: 1 pm	NAME: Joaquin/Cianfichi
DESCRIPTION	LOCATION	COMMENTS
RODENT ACTIVITY		none
LEVEE CROWN FALL (water run-off)	328,310, 195- 196, 176-177	Several spots on the paved ferry road have settled from the heavy grain truck use this season. Heavy ponding during rain
ROAD CONDITIONS		AWR AB needs to be bladed after the rains
SLOUGH, EROSION, CRACKING	440, 462	Down ramp at 440 has crack running perpendicular. Splash berm at 462 has small settlement crack
DEBRI LANDSIDE	60	Tree down at station 60 just off the toe
DEBRI WATERSIDE	462, 410, 409, 455, 709	462, 410, 409, 455 logs on levee below mean waterline. 709 old barge.
SEEPS AND BOILS	440-450, 467	467 running. 440- 450 wet on toe.
TOE DITCHES		have been cleaned.
VEGETAION OBSTRUCTIONS	multiple	Cattle are out on parts controlling the vegetation. Several small saplings coming up that need to be removed WS. 135, 125,55,40.5,40,39.5,2,617,510.104,103,775,753,685,670
SUITABLE GROUND COVER CONDITIONS		weeds have died back. Grasses are established all around the levee
ROCK ARMOR CONDITIONS		Good condition
TOE ROAD CONDITIONS		toe roads are wet due to rains. Most are still drivable.
ACCESS AND ENCROACHMENTS	435	435 light house at Jersey point.
PROFILE OR CROSS SECTION CHANGES		No noticeable changes