

RD 830 LEVEE INSPECTION

DATE: 3/27/20	TIME: 9 am	NAME: McGormley
DESCRIPTION	LOCATION	COMMENTS
RODENT ACTIVITY	370-380, 199,150-160	370-380 gopher activity landside slope, 199, 150-160 ground squirrel activity toe and slope
LEVEE CROWN FALL (water run-off)	328,310, 195- 196, 176-177	Several spots on the paved ferry road have settled from the heavy grain truck use this season.
ROAD CONDITIONS		Good condition
SLOUGH, EROSION, CRACKING	440, 464,	Down ramp at 440 has crack running perpendicular. Splash berm at 464 has small settlement crack.
DEBRI LANDSIDE		Clear
DEBRI WATERSIDE	462, 410, 409, 455, 709	462, 410, 409, 455 logs on levee below mean waterline. 709 old barge.
SEEPS AND BOILS	442, 467	467 running. 442 wet on toe.
TOE DITCHES	445-455	Toe ditch has been cleaned
VEGETAION OBSTRUCTIONS		Cattle are out on parts controlling the vegetation.
SUITABLE GROUND COVER CONDITIONS		weeds have died back. Grasses are established all around the levee
ROCK ARMOR CONDITIONS		Good condition
TOE ROAD CONDITIONS		Good condition
ACCESS AND ENCROACHMENTS	435	435 light house at Jersey point.
PROFILE OR CROSS SECTION CHANGES		No noticeable changes