

Jersey Island TDS and EC Report

6/4/15

Tester: Marquis

Test Location	EC	Temp. C	TDS mg/L	Time	Air Temp	
1. Blind Point Siphon 547 + 00	2600	20.0	1327	1000	66	
2. Station 580 + 00	3410	20.3	1755	1011	68	
3. Twin Siphon 692 + 00	1623	20.6	812	1034	70	
4. Farm pump 809 + 00	1454	22.2	724	1052	70	
5. Main ditch at Ferry rd. intersection	2810	20.0	1430	1100	70	
6. 15 " siphon 211 + 00	1345	21.9	669	1111	70	
7. Ferry Siphon 324 + 00	1086	21.9	536	1119	72	
8. False river Siphon 396 + 00	1777	22.7	892	1143	72	
9. Jersey Point 435 + 00	1605	21.1	803	1134	72	
10. Main Discharge pumps	1991	18.4	1003	0911	64	
11. Spring Corrals	1091	18.7	539	904	63	
12. Main Corrals	2049	19.5	1034	855	63	
13. Lake Williams	3640	21.0	1881	930	64	
14. Shop Well	2580	20.4	1314	915	64	
15. Moss Well	2540	19.6	1294	1105	70	